

RENEW $\frac{1}{4}$ COR 36 1/2 T 25 S

RGW RSW

FOUND - BOTH SETS RECORDED BY KERR
1951. 18" NAW 20" FIR 377°W 7.9'
STANDING & IN GOOD CONDITION SHOWS
GOOD SCORING. 11" FIR N 26° E 11'
NOW DOWN & DOWN HILL MAY HAVE BEEN
PUSHED DOWN BY CAT. I FIND NO TRACE
OF ORIG. NE SET. IT ALSO MAY HAVE
BEEN PUSHED BY CAT.

SET BRASS CAP AT CORNER MKD
COUNTY SURVEYORS OFFICE 1959

RGW RSW

$\frac{1}{4}$ 336 1/2 T 25 S

NEW SET
10" R. FIR BEARS N 40° E 68.5'
SET BY $\frac{1}{4}$ 331 CORNER

NOTE - N E FENCE IS 15' WEST OF
COR.

DIETZGEN NO. 386.6

? THIS CORNER STILL
UNDER INVESTIGATION.
- BUILDING FRAME MARKS
CORNER

APRIL 28-59

W. D.

FILED
RECEIVED

APR 23 1959

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No.

49/123.2