

REN. T 25 S R 6 W

MOST NORTHERLY
N.W. COR. D.L.C. # 51

AT COR. FD. $3\frac{1}{4}$ " IRON BOLT IN
FENCE CORNER. - FENCES SOUTH, EAST
& NORTH WEST.

FD. ROTTED FIR STUMP N $40\frac{1}{2}$ ° W
13² FT. SCRIBING VISIBLE ON PORTION
OF OLD FACE "5" & "BT."

THIS TREE WAS MARKED BY GERMOND.
NO TRACE FD. OF GERMOND'S N.E. B.T.
NO TRACE OF DRIG. B.T. FD.

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1962 T 25 S R 6 W N N W
COR. D.L.C. # 51" SET BOLT
BACK ALONGSIDE BRASS CAP.

BLAZE & SCRIBE 2 NEW B.T.'S:

13" WHITE OAK N $72\frac{1}{2}$ ° E 40³ FT.
MKD. "NNW D.L.C. 51 CS BT"

14" WHITE OAK S 30° W 19⁵ FT.
MKD. "NNW D.L.C. 51 CS BT"

JULY 23, 1962

M.G.

V.T.

M.S.

Milo E. Godfrey

Renewed Cor. # 55

+ * ✓

C.S. FILE NO. 49/123-10