

REN. T 25 SR 6 W

1/4 S 1/2 S 3 1/2

FD. BURNED FIR STUMP S 59° W  
15 1/2 FT. ENDS OF SCRIBE MKS. VISIBLE  
ALONG UNBURNED EDGE OF BADLY  
CHARRED FACE.

FD. STUMP HOLE & PART OF FIR  
STUMP N 63° E 32° FT. (IN PLACE)  
TOO MUCH GONE TO FIND SCARS  
OR SCRIBING.

(THESE 2 TREES MKD. BY STEWART  
IN 1922)

FD. STUMP HOLE S 87° E 72 FT.  
(ORIG. B.T.)

NO TRACE FD. OF ORIG. N.W.B.T.  
AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1962 T 25 SR 6 W 1/4 S 1/2 S"

BLAZE & SCRIBE NEW TREES:

4" MADRONE N 78° E 36 1/2 FT.  
MKD. "1/4 S 2 CS BT"

18" DOUG. FIR S 33° W 93° FT.  
MKD. "1/4 S 3 CS BT"

COR. IS IN FENCE COR. - FENCES  
N., S., & WEST.

NOV. 15, 1962

M.G.

M.S.

*Milo E. Godfrey*

+ \* O ✓

C. S. File No. 49/1234 41