

Renewal T255 R6W 532/533 JAN. 29, 1963
T265 55/54

Fd. at the CORNER of Sections 32 & 33 of

T255 R6W and sections 4 & 5 of T265 R6W a

32" White Oak SNAG that BEARS S52°E 117[±] ft
with scribe marks "T S", "R", "S" & "BT", also

Fd. a Black Oak STUMP S. 4°W. 15[±] ft, Rotted,
No scribe. a 25" White Oak tree N. 83°W.

112[±] ft. Showing good SCAR. And a 20" White

Oak tree N. 84°E. 53[±] ft Shows a faint SCAR.

Set a 1" Iron pipe and Brass cap for COR.

Mkd. County Surveyors Office 1963 T255

T265 R6W 532/533 " and New BT's.
55/54

16" Black Oak BEARS S49°E 69[±] ft

Mkd "T265 R6W 54 CS BT"

13" White Oak BEARS S. 29°W. 29[±] ft

Mkd "T265 R6W 55 CS BT"

14" White Oak BEARS N. 39°W 10[±] ft

Mkd. " T255 R6W 532 CS BT"

15" White Oak BEARS N. 57°E. 26[±] ft

Mkd "T255 R6W 533 CS BT"

CORNER is 1^o ft South of East-West
Fence Line, approx. 1 chn. West of Top

of Ridge Bearing North & South.

✓ JAN. 29, 1963

M.G.
V.T.
M.S.

✕ Milo E. Godfrey S. No. 49/123 - 72