

RENEW  $\frac{514}{819}$  T243 R5W

FOUND - 20" NOW 24" FIR STUMP AS RECORDED BY B.B. - 1929 - IT OPEN & FIND GOOD SCRIBING "BT" ORIG. 20" NOW 40" B.OAK 560° E 40' SHOWS OLD SCAR I DO NOT OPEN. ORIG 18" NOW 36" B.OAK N 62° W 33.7 (IT FIND SHOULD BE 40.5) SHOWS GOOD SCRIBING "S" ON OLD FACE ORKE 10" NOW 20" PARTLY ROTTED OAK STUMP SHOW 356° SHOWS REVERSE SCRIBING "T".

NOTE - COR. THUS



SET BRASS CAP AT CORNER MKO

55 | 54 T 243 R5W COUNTY SURVEYORS  
58 | 59 OFFICE, 1959

NEW BTJ.

8" R FIR BEARS S 51° W 14 L'  
SCRIBED 58 T 243 R5W COR BT

40" B.O. 560° E 60'  
SCRIBED 59 T 243 R5W COR BT

8" R. FIR BEARS N 61° W 80'  
SCRIBED 55 T 243 R5W COR BT

10" LAUREL BEARS N 24° E 28.5'  
SCRIBED 54 T 243 R5W COR BT

AUG. 4-59  
J.B. M.G.  
C.P.

✓ V.C. S. File No. 49/424 VAR. 20 1/2

DIETZGEN NO. 388-6