

RENEW $\frac{6}{7} \frac{5}{8}$ T245 R5W

FOUND - ORIG. 12" NOW 30" B. OAK SNAG

N58°W 122' OPENED YEARS AGO

OLD FACES ROTTED NO SCRIBING FD

NO TRACE OF ORIG. SE BT FD (INFIELD)

I FIND DEPRESSION, WHICH MAY HAVE

BEEEN LOCATON OF ORIG. SW BT

RECORD CALLS FOR TWO BTS. TO NW

I BELIEVE IT SHOULD READ S75°W

216.5' I ALSO FIND 48" W. OAK CHECKS

ORIG. BEARING FOR N E BT DIST 441.2'

SHOWS OLD AXE WORK CENTER ROTTED

NO SCRIBING FD.

SET BRASS CAP AT COR. MKD. COUNTY
SURVEYORS OFFICE. 1959 $\frac{56}{57}$ | $\frac{55}{58}$

T245 R5W

NEW BTS.

11" B. OAK (DOUBLE) BEARS S73°W 24'

SCRIBED S77245 R5W CS BT

7" W. OAK BEARS N 50° W 50.7'

SCRIBED S8 T245 R5W CS BT

16" W. OAK BEARS N 7° E 29.5'

SCRIBED S5 T245 R5W CS BT

THIS TREE SHOWS SCRIBE MARKS MADE
SEVERAL YEARS AGO. NOT OF RECORD
FACES TO CORNER.

4" W. OAK BEARS S54° E 85.3'

SCRIBED S8 CS BT

CS 49 | 124-9

*

∨ ∨