

RENEW

35/36  
2/1

T 243  
R 5 W

FOUND - No TRUS  
 STEWARTS BEATS 18" NEW 32" STUMP  
 SHOWS GOOD SCRAPING "C" 2" 18"  
 NEW 80" FIR STUMP 55" E 73.0'  
 SHOWS GOOD SCRAPING DO NOT OPEN  
 FINELY 22" FIR 76.5" E 37.0' SHOWS  
 GOOD SCRAPING "V" NOTED - DUSTS  
 TO B.T.S. RECORDED BY STEWART  
 ARE MEASURED BY SCOTT.

SET BRASS CAP AT CORNER MARK  
 COUNTY SURVEYORS OFFICE IS 6  
~~SET~~ TRUS  
 R 5 W  
 SR 51 TRUS

NEW SET  
 8" R. FIR BEAMS 77.0 W 43.0'  
 SCRIBED 2 BEAMS 45.0 W 45.0'  
 11" R. FIR BEAMS 45.0 W 45.0'  
 SCRIBED 2 TRUS 45.0 W 45.0'  
 7" R. FIR BEAMS 54.0 W 50.0'  
 SCRIBED 51 TRUS 45.0 W 45.0'

KAR 20 4' MAR 4-60  
 G. W.  
 S. W.  
 P. D.

DIETZGEN NO. 385-6

C. S. File No. 49/129.37