

T 24 S R 5 W

$\frac{1}{4}$  S  $\frac{29}{32}$

FD. W. OAK (NOW 25" DIAM)  
N 69 $\frac{1}{2}$ ° E (REC. N 67 $\frac{1}{2}$ ° E) 71.3 FT. TREE  
HAD BEEN PREVIOUSLY OPENED & GROWN  
OVER AGAIN - PROBABLY ROTTED INSIDE,  
DID NOT OPEN.

FD. W. OAK (NOW 24" DIAM.)  
S 73° W (REC. S 71° W) 53.5 FT.  
CUT OPEN & FD. PORTIONS OF REVERSE  
SCRIBING - PART OF "B" & PART OF "T".  
TREE ROTTEN INSIDE.

AT COR, SET IRON PIPE WITH  
BRASS CAP MKD "COUNTY SURVEYOR'S  
OFFICE, 1960 T 24 S R 5 W  $\frac{1}{4}$  S  $\frac{29}{32}$ "

BLAZE & SCRIBE NEW TREES:

10" W. OAK N 66° E 58.0 FT  
"  $\frac{1}{4}$  S 29 CS BT"

12" W. OAK S 45° W 90.8 FT.  
"  $\frac{1}{4}$  S 32 CS BT"

SMALL CREEK APPROX 50 FT. EAST  
OF COR.

VAR 20 $\frac{1}{2}$

MARCH 8 - 60

J. B.

M. G.

C. P.

\*  
✓ C. S. File No. 49/124-33