


RENEW $\frac{1}{4}$ COR 30 T255 R5W
31

FOUND - I BELIEVE WE HAVE
FOUND BOTH ORIG. B.T.S. NO SCRIBING FB
ON EITHER BT ORIG. 12" NEW 22"
W. OAK N51'W 78.5' OPENED ABOUT
40 YEARS AGO OLD FACE ROTTED.
RIG. SW BT NOW DOWN & BADLY
ROTTED. CHECKS RECORD BEARING &
DIST.

FENCE COR. THIS 

NEW B.T.S.

10" R. FIR BEARS N63'E 41'

SCRIBED $\frac{1}{4}$ S 30 CS BT

7" R. FIR BEARS S40'W 81'

SCRIBED $\frac{1}{4}$ S 31 CS BT

SET BRASS CAP AT COR. MK'D

COUNTY SURVEYORS OFFICE, 1960

$\frac{1}{4}$ S 30 T255 R5W
531

MAY 16-60

J. B.

M. G.

C. P.

*

CS 49/124-60