

RENEW $\frac{22}{27} \frac{23}{26}$ T 255 R 5W

FOUND - NOW 30" STUMP 59 2 1/2' W

16.6' SHOWS GOOD BARK SCRIBING

"BT" I ALSO FIND NOW 30" STUMP

N 49 1/4° E 50.3' BARK GONE NO SCRIBING

FOUND. FIND 30" FIR STUMP

59 9 1/2° E 36.6' SHOWS GOOD BARK

SCRIBING BT

NOTE: - COR. FENCE POST AT

SEA. COR. SET BRASS CAP ALONG-

SIDE. & MARKED COUNTY SURVEYORS

OFFICE 1960 $\frac{524}{527} \frac{523}{526}$ T 255 R 5W

NEW BTS.

5" R. FIR BEARS S 68° W 12.7'

SCRIBED 527 T 255 R 5W CSBT

10" R. FIR BEARS N 6° W 43.9'

SCRIBED 522 T 255 R 5W CSBT

JUNE 13

VAR 20 1/2°

J.B.

← P.

*
✓ CS 49/124-65