

REN. T25SR5W W.C. S26/S25  
TO S35/S36

AT COR. ED. FIR TREE (NOW 40" DIA.)  
(30" WHEN MKD.) PREVIOUSLY OPENED ON  
S.E. FACE. SCRIBING VISIBLE "T25SR5W  
S36". SCARS VISIBLE ON N.E., N.W.,  
& S.W. FACES.

SET IRON PIPE WITH BRASS CAP

MKD. "COUNTY SURVEYOR'S OFFICE 1962

T25SR5W WC  $\frac{S26}{S35} | \frac{S25}{S36}$  12 FT. N.  
TO COR. 12 FT. SOUTH OF C.D.R.  
TREE"

BLAZE & SCRIBE BEARING TREES:

16" DOUGLAS FIR S 7° E 7 $\frac{3}{4}$  FT.

MKD. "T25SR5W WC S36 CS BT"

24" DOUGLAS FIR S 57° W 19 $\frac{8}{16}$  FT.

MKD. "T25SR5W WC S35 CS BT"

8" HEMLOCK N 22° W 46 $\frac{6}{16}$  FT.

MKD. "T25SR5W WC S26 CS BT"

NO TREES AVAILABLE TO N.E.

C.D.R. LIES APPROX. 25 FT. W. OF STEEP

DRAW SLOPING NORTH & APPROX. 10 FT.

WEST OF N. & S. FENCE LINE, ON VERY

STEEP N.E. SLOPE.

SEPT. 21, 1962

M.G.

M.S.

*Paul E. Goffroy*

C.S. No. 49/124<sup>78</sup>