

REN. T 26 S R 5 W 1/4 S 11
S 14
THIS IS ALSO MEANDER COR. (RT. BANK)

FD. BRASS CAP SET IN 1954;
IN PLACE, BUT BENT OVER.

FD. 11" WHITE OAK S 79 1/4° E 332 3/4 FT.
ALIVE & IN GOOD CONDITION. - SCARS PLAIN.

FD. 30" BLACK OAK N 73 1/4° W 201 0 FT.
STILL STANDING - BUT MOST OF
SOUTH FACE & BLAZES BURNED AWAY,
SOME SCRIBING STILL VISIBLE ON EDGE
OF SCARS.

FD. BURNED REMAINS OF OAK
STUMP S 43° W 67 1/2 FT.

DROVE STEEL FENCE POST
ALONGSIDE OF BRASS CAP.

BLAZE & SCRIBE 2 NEW TREES:
17" BLACK OAK S 27 1/2° W 106 3/4 FT.

MKD. " 1/4 S 14 CS BT "

34" BLACK OAK N 10° W 219 0 FT.

MKD. " 1/4 S 11 CS BT "

COR. IS IN CULTIVATED FIELD
APPROXIMATELY 50 FT. EAST OF RIVER
BANK.

SEE
REN. # 35

FEB. 5, 1964

Phil E. Godfrey

M.G.
W.S.
M.S.

X X ✓

C. S. File No. 13/25-29

T 26 S R 5 W

NOT FD.

M.C.

RIGHT BANK

S14
S23

✓

FEB. 5, 1964

M.G.
W.S.
M.S.

Wm. C. Dodson

DIETZEN NO. 385-6

FILED
RECEIVED

FEB 5 1964

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.