

T 26 S R 5 W

CORNERS FOUND O.K.

① COR. $\frac{14}{23} | \frac{13}{24}$ BRASS CAP &
SECS. ALL B.T.'S MKD. IN 1958 STILL
IN GOOD CONDITION - REN. #49 ✓

② $\frac{1}{4} \frac{5}{23} | \frac{5}{24}$ (WIT. COR. TO $\frac{1}{4}$ COR.)
BRASS CAP & BOTH B.T.'S
MKD. IN 1958 STILL IN GOOD
CONDITION. - SEE REN. #52 ✓

③ MEANDER (RIGHT BANK) $\frac{525}{525}$
COR. (WEST OF $\frac{1}{4}$ COR.)
FD. BRASS CAP & BOTH B.T.'S
MARKED IN 1958 IN GOOD CONDITION.
(RESET BRASS CAP WHICH HAD BEEN
PARTIALLY WASHED OUT BY HIGH WATER)
ORIG. PINE B.T. NOW DEAD.
SEE RENEWAL #44 ✓

~~SEARCHED FOR & NOT FD.~~

① COR. $\frac{23}{26} | \frac{24}{25}$ ✓

② M.C. $\frac{5}{26} | \frac{5}{25}$ ✓

③ S.W. COR. D.L.C. #39 ✓

FEB. 6, 1964

M.G.

W.S.

M.S.

Milo E. Goffey
File No. 89/885 130