

5251  
RENEW 5/15/51 AT 325 R3W 446

FD-ORIG. 20'x10"xs" STONE 15" IN  
GROUND & MARKED AS RECORDED. I ALSO  
FIND NOW 8" FIR DOWN & MOSTLY ROTTED  
THAT CHECKS BEARING DIST. FOR ORIG  
N W BT. NO SCREWS FOUND. NO TRACE  
OF OTHER BPTS. FOUND. THE SW BT  
MAY HAVE BEEN WASHED OUT. THE  
REST OF BPTS. WOULD BE IN FIELD.

GET BRASS CAP ALONGSIDE CAR.  
STATE ROAD COUNTY SURVEYORS OFFICE

5251  
5/15/51 T 325 R 3 W

NOTE - CORNER UNDER N S TREE

NEW BPTS.

16" HEMLOCK BEARS S 2° W 91.1'  
SCRIBED 511 T 325 R 3 W C S BT

18" R. FIR BEARS N 86° W 203.9'  
SCRIBED 52 T 325 R 3 W C S BT

12" W. FIR BEARS S 20° E 263.6'  
SCRIBED 512 T 325 R 3 W C S BT

DIETZGEN NO. 385-6

\*

FILED

RECEIVED

FEB 26 1959

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

✓ C. S. File No. 49/136-2