

RENEW  $\frac{1}{4}$  CAR 23/24 T 295 RW

FOUND - 1" I.P. AT CAR & NOW 8" LABEL  
SKIVE 30" - NOW IN AG - SHOWS GOOD  
BARK SCRIBING "S" I DO NOT FIND  
MARKS NE BT

NEW BTS.

12" R. FIR BEARS S 10° W 142  
SCRIBED S 25 T 295 BT

23" R. FIR BEARS N 3° E 792  
SCRIBED S 26 T 295 BT

APRIL 23-62

DIETZEN NO. 385-5

RENEW  $\frac{23}{26}$  T 295 RW

FOUND -  $\frac{3}{4}$ " I.P. 6" UNDER SURFACE  
AT CAR.

50" NOW 50" R. FIR N 85° E 825 SHOWS  
GOOD BARK SCRIBING. SW & NW BTS.  
NOW STAMPS SHOW BARK SCRIBING

SET BRASS CAP ALONGSIDE CAR I.P.  
AND MARK ~~521/524~~

521/525 T 295 RW

COUNTY SURVEYORS OFFICE 1962

NEW BTS.

12" R. FIR BEARS S 50° E 320  
SCRIBED S 25 T 295 RW CS BT

8" W OAK BEARS N 59° W 1226  
SCRIBED S 23 T 295 RW

20" LAUREL BEARS S 17° W 757  
SCRIBED S 26 T 295 RW CS BT

G. S. File No. 49/189-50