

RENEW W  $\frac{1}{4}$  S 34 $\frac{1}{2}$  T 29 S R 7 W

FOUND - BRASS CAP AT COR.  $\frac{3}{4}$   
SE BT IS OK WE FIND NO TRACE  
OF NE BT.

NEW BT

13' W. FIR BEARS S 81° E 7.0'  
SCRIBED W  $\frac{1}{4}$  S 34 $\frac{1}{2}$  CS BT



RENEW  $\frac{1}{4}$  COR 34 $\frac{1}{2}$  | 35 T 29 S R 7 W

FOUND - BRASS CAP AT COR. AND  
SE BT WE FIND NO TRACE OF  
NW BT.

NEW BT.

38" R. FIR BEARS S 49° W 13.5'  
(BARK SCRIBED  $\frac{1}{4}$  S 34 $\frac{1}{2}$  CS WOOD SCRIBED  
"BT")



RENEW E  $\frac{1}{4}$  COR 34 T 29 S R 7 W

FOUND - BRASS CAP AT COR.  
AND NW BT. SW BT NOW DOWN

NEW BT.

18" R. FIR BEARS N 87° E 7.5'  
SCRIBED S 34 $\frac{1}{2}$  CS BT

FILED + \*  
RECEIVED O \*

MAY 11 1962

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No.

49/139-S4

DIETZGEN NO. 3855-6