

T 295 R8W R7W 327

RENEW 36 | 31 T 29 1/2 S

FOUND - BRASS CAP AT CORNER
BOTH B.T.S. NE BT NOW STUMP
SHOWS SCRIBING. WE OPEN N W
BT & FIND GOOD SCRIBING.

NEW B.T.S.
13" R. FIR BEARS N 150 E 33.7
SCRIBED T 29 1/2 S R7W 531 C 5 BT

8" W. FIR BEARS 572' W 37.1'
SCRIBED T 30 S 56 R7W C 5 BT

1575

+ * ✓

RENEW 1/4 COR 7/8 T 295 R7W

FOUND - BRASS CAP AT CORNER
& 8" UNDER SURFACE SE BT
NOW STUMP ONLY SW BT IS OK.
SHOWS GOOD SCRIBING.

NOTE - 22' W.O. BEARS 55' E
1560 WE DO NOT SCRIBE THIS HERE
WE SET 3/4" I.P. SOUTH 23.8'
FROM COR. 4 & UNDER EAST WEST
FENCE.

YAR 20 1/2

4 1/2 26-92

4 1/2
4 1/2

+ * ✓

C.S. File No. 49/139-84

DIETZEN NO. 3695-6