

Recovery #17 21/22 T29286W

Found:

16" D. Fire mark 16" N75E 25  
shows good seam

20" D. Fire mark 22" S62W 39  
shows good seam

Also old scribbled post. Scribbled  
1/2 31 13CS

After good search with Metal  
Finder, I find no Iron Pipe

Recovery

Set Brass cap at 1/4 cor 1970  
county surveyors office

T29286W

1/4

321/522

1971

BTs at + Tagged

2-12-71

~~J.W.B.~~  
J.W.B.

O.M.  
J.W.B.

#214

SEE N. FD. OVER C.S. 49/139 141

DIETZGEN NO. 385-6