

REN.

T 21 S R 6 W

$\frac{1}{4}$ S $\frac{1}{4}$ S
15¹⁴

FD. BADLY ROTTED HEMLOCK

STUMP S 53° E 11² FT. SCRIBING
VISIBLE ON OLD FACE " $\frac{1}{4}$ S"

FD. BADLY ROTTED HEMLOCK

STUMP S 57° W 16² FT. FD FRAGMENT
OF SCRIBING. PART OF "B"

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SUR-
VEYOR'S OFFICE 1962 T 21 S R 6 W
 $\frac{1}{4}$ S $\frac{1}{4}$ S"
15¹⁴

BLAZE & SCRIBE NEW TREES:

5" HEMLOCK S 41° W 10⁸ FT.

MKD. " $\frac{1}{4}$ S 15 CS BT"

5" HEMLOCK N 30° E 6⁰ FT.

MKD. " $\frac{1}{4}$ S 14 CS BT"

COR. LIES ON STEEP N.W. SLOPE
APPROX. 100 FT. SOUTH OF SMALL STREAM

MAY 7, 1962

M.G.

V.T.

C.P.

M.G.
ROYER

[Handwritten signature]

+ * 9

C. S. File No.

19/143-29