

REN.

T22S R6W

$\frac{1}{4}$ S⁺S
19⁺20

FD. CEDAR STUMP (NOW 48" DIAM)

- APPROX. 24" WHEN SCRIBED - N 45° E 65³
FT. HAS BEEN PREVIOUSLY OPENED &
SCRIBING " $\frac{1}{4}$ S" PLAINLY VISIBLE

FD SHATTERED FIR STUMP
(NOW 48" DIAM.) S 50° W - INSTEAD OF
N 50° W - 15⁸ FT. NO SCAR OR SCRIBING
FD. - NO TRACE OF STUMP FD. TO THE
N.W.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "COUNTY SURVEYOR'S OFFICE
1961 T22SR6W $\frac{1}{4}$ S⁺S
19⁺20

BLAZE & SCRIBE NEW TREES AS
FOLLOWS:

12" DOUG. FIR S 89° E 24^L FT.
MKD. " $\frac{1}{4}$ S 20 CS BT"

21" DOUG. FIR N 55¹/₂° W 44⁵ FT.
MKD. " $\frac{1}{4}$ S 19 CS BT"

AUG. 22, 1961

M.G.
V.I.T.
C.P.

Milo E. [Signature]

C.S. No. 49/143

60

* + ✓