

51 - 70" OAK
RENEW $\frac{1}{4}$ COR. 36/31 T 275

R6 R5

FOUND - BOTH BTS. AS RECORDED BY
BOYER. 1 DRILL, 20" NOW 40" OAK
IN A LOWER SECTION PREVIOUSLY OPENED
SHOWS GOOD SCRIBING 'BT' IN OPEN PART
OF BOYER'S BTS. I FIND GOOD SCRIBING
THE NW BT CHECKS BEARING & DIST.
THE SW BT SHOULD BE $S 30^{\circ} E$ 30.9'

NOTE - A EAST WEST FENCE
IS 2' SOUTH OF CORNER.

SET BRASS CAP AT CORNER, MAD
COUNTY SURVEYORS OFFICE 1969

$\frac{1}{4}$ S36 | S31 T 275
R6 W | R5 W

NEW BTS.

7" W. OAK BEARS $S 69^{\circ} W$ 22.8'
SCRIBED $\frac{1}{4}$ S 36 C S BT

7" W. OAK BEARS $S 75^{\circ} E$ 13.0'
SCRIBED $\frac{1}{4}$ S 31 C S BT

VAR 204°

APRIL 3-59
J. BYRON
M. GODFREY
S. BROWN

DIETZGEN NO. 385-6

✓✓✓
C. S. File No. 49/145-3