


Township 31 South, Range 9 West, W.M.

The $\frac{1}{4}$ corner between Sections 7 and 18 has two original bearing trees. The fir 12 inches, S80°W. 40 links is now a snag and unlikely to withstand logging operation. The notes for the original fir 12 inches, N30°E, 67 links, should read fir 12 inches, N12°E, 67 links.

I set a 4 inch square post for this corner and mark a fir 36 inches, S64°E, 19.0 feet, $\frac{1}{4}$ S. B.T.

April 20, 1959


C. S. Lehmanowsky
Engineer, Oregon 1768