

COUNTY SURVEYORS FILE DATA  
DO NOT REMOVE FROM OFFICE


# METES & BOUNDS SURVEY TO SET CORNERS IN SECTION 21, TWP. 26 S, RGE. 4 W, W.M.

SURVEYED FOR: GEORGE STRADER  
SURVEYED BY: G. R. LECKLIDER-ENG'R.

OCTOBER, 1959  
SCALE: 1" = 100'

○ DENOTES STEEL TUBE WITH CAP SET  
⊗ DENOTES "T" BAR WITH CAP SET

NOTE: Bearings based on section line as being due East & West



FILED *[Signature]*  
RECEIVED

OCT 9 1959

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

