

February 6, 1961

SECTION CORNERS

The following corners were re-established in Township 27 South, Range 1 West, Willamette Meridian; BY: T. E. SHRUM, JR. R.E. 4287

SECTION CORNER 17,18,19,20

FOUND: 12" Hemlock - N 72°W - 24.4' - Dead
 14" Hemlock - S 41°W - 60.7' - Dead

SET: 46" Cedar - N 45°E - 210.1'
 28" Cedar - S 89°E - 154.8'

SECTION CORNER 19,20,29,30

FOUND: Stone Marked as called for in G. L. O. Notes
 All trees have been destroyed

SET: 16" Doug. Fir - S 82°W - 84.3'
 33" Cedar - S 21°E - 110.5'
 8" Hemlock - N 43°E - 100.1'

1/4 SECTION CORNER 17,20

FOUND: 14" Doug. Fir - N 62°E - 26.4 - Rotten
 14" Doug. Fir - S 06°W - 39.6 - Down

SET: 3/4" X 36" Iron Rod
 12" Doug. Fir - S 26 1/2°W - 38.7'

1/4 SECTION CORNER 19,20

FOUND: Stone Marked as called for in G.L.O. Notes
 36" Doug. Fir - N 32°W - 15.2' (S 32W in original Notes)
 36" Doug. Fir - S 48°E - 17.8' (N 48E in original Notes)

SET: 7" Hemlock - S 41°W - 55.7'

FILED
RECEIVED

Bud Shrum

FEB 7 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.



✓ C. S. File No. 51/175