

T23S RGW

Wilford N. Haines

June 29, 1962

at Cor. 675 T.23S, RGW on 5th. standard parallel

Fd. Brass cap set by G.L.O. pulled out

Set back in same hole

orig. fir B.T. Now 6.0 ft stump

Bears S25°E. 5.3 ft. to face of scribe

New B.Ts. by G.L.O.

16" Hemlock S29°E. 53.3 ft. (Not 47-1Ks)

10" Hemlock S31°W 47-1Ks (Not 79-1Ks)

this tree is down

○+VV

At C.C. 31+32 T22S RGW 5th. stand parallel

Fd. my cor. + iron with G.L.O. Brass alongside in
A pill of rocks.

Fd. 18" fir B.T. N.36½W. 45.4 ft.

24" fir stump scribed C.C. S.32 B.T.
N20°E. 48.1 ft.

NOT
RENEWED BY HAINES
REPORTED FOUND
BUT NOT RECORDED

○+VV

¼ S 8/9 T23S RGW

Fd. G.L.O. Brass cap

12" chinquapin S70°E 43-1Ks is gone

10" Fir S84°W 89-1Ks Fire or bug Killed (Rec. S48°W
v.R.)

Scribed New trees

16" fir S.04°E. 31.0 ft.

10" fir N.87°W. 42.7 ft.

FILED
RECEIVED

JUN 29 1962

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

REGISTERED
OREGON
LAND SURVEYOR

Wilford N. Haines

MAY 7, 1948
WILFORD N. HAINES
239

C. S. File No. 51/222-3