

REN. T 21 S R 8 W COR SECS 34/35
(ON N LINE SEC. 2, T 22 S R 8 W)

AT COR. FD. BRASS CAP SET IN
1952 - (UNDER UPROOTED FIR 36"
IN DIAM.)

FD. 7" HEMLOCK (NOW 10" DIAM.)
N 78 $\frac{1}{2}$ ° W 23 $\frac{1}{2}$ FT. - TREE ALIVE
& IN GOOD CONDITION.

THE 55" FIR N 30° E 29 $\frac{1}{2}$ FT
IS NOW A STUMP - SAWED OFF 2 FT.
ABOVE GROUND.

THE 47" FIR N 35 $\frac{1}{2}$ ° E 60 $\frac{1}{2}$ FT.
IS NOW A SHATTERED SNAG,

BLAZE & SCRIBE NEW TREE:

10" HEMLOCK N 7 $\frac{1}{2}$ ° W 68° FT.

MKD. "T 21 S R 8 W S 34 CS BT"

NO TREES AVAILABLE IN SEC,
35.

SEPT. 17, 1963

M.G.

W.S.

M.S.

W. E. Coffey

FD. D.K. N $\frac{1}{4}$ S 2 T 22 S R 8 W

BRASS CAP & BOTH B.T.'S
IN GOOD CONDITION.

NOTE - 70" FIR IS S 19 $\frac{1}{2}$ ° E
89 $\frac{1}{2}$ FT. (NOT S 14 $\frac{1}{2}$ ° W)

U.S. File No. 52/14³¹