

REN. T23SR8W C.C. 56/55

(ON SOUTH LINE T22SR8W)
FD. FIR TREE (NOW 58" DIAM.)

N36°W (NOT N44°W) 39 1/2 FT. CUT OPEN
SCAR & MD. GOOD SCRIBING. - TREE ALIVE
& IN GOOD CONDITION.

FD. FIR TREE (NOW 34" DIAM.)

S20°W 27 1/2 FT. - SHOWS VERY GOOD
AXE SCAR. - TREE ALIVE & IN GOOD CONDITION.

FD. BADLY ROTTED WHITE FIR STUMP
N40°E 34 3/4 FT. - FD. PORTION OF FLAT
FACE & AXE MKS. BUT NO SCRIBING.

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1962 T22S T23SR8W
C.C. 56/55"

BLAZE & SCRIBE ONE NEW TREE:

10° DOUG. FIR S 74° E 27° FT.
MKD. "T23SR8W C.C. 55 CS BT"

FD. 1 1/4" IRON PIPE
15" ABOVE GROUND WITH CAP STAMPED
"S32" N86°E 3 1/2 FT. FROM COR. AS SET.
56/55

JAN. 22, 1963

M.G.
V.T.
M.S.

Milo C. Godfrey

+X✓

C.S. File No. 52/14-52