

REN. T22SR8W CDR. 29/28
SECS. 32/35

AT COR. FD, BRASS CAP SET BY
CADASTRAL SURVEY 1960.

FD, WHITE FIR (NOW 7" DIAM.)
N 38°W 29 $\frac{1}{2}$ FT. - SCRIBING VISIBLE
IN NEARLY HEALED OVER SCAR.

FD, 9" DOUG. FIR S 35°W 67 $\frac{3}{4}$ FT.
- SCAR PITCHED OVER.

FD, MADRONE (NOW 30" DIAM.)
S 52°W 51 $\frac{1}{2}$ FT. - 1 BLAZE
* RESCRIBE THIS TREE "T22S
R8W S32 CS BT"

FD, MADRONE (NOW 24" DIAM.)
S 61°E 33 $\frac{1}{2}$ FT. - 1 BLAZE
* RESCRIBE THIS TREE "T22S
R8W S33 CS BT"

FD, 48" DOUG. FIR (NOT CALLED
FOR IN NOTES) N 68°E 44 $\frac{1}{2}$ FT.
MKD. "T22S R8W S28 BT"

SEPT. 12, 1963

M.G.

M.S.

Milo E. Godfrey

+ X^o

(SEE OVER)

C.S. File No.

52/141^N