

REN. T22 S R5 849W S1/56
S12/57

AT COR. FD. 1" IRON PIPE
EXTENDING 18" ABOVE GROUND SURFACE

FD. DEAD FIR (NOW 45" DIAM.)
N 45° W 4⁰ FT. - BARK SCRIBING
(NOT ORIG.) FD. "T225 R9W S1"
NO ORIG. SCRIBING FD. - BARK BADLY
BURNED.

FD. DEAD FIR (NOW 60" DIAM.)
N 32° E 15⁸ FT. - BARK SCRIBING
(NOT ORIG.) FD. "T225 R8W S6 BT"
NO ORIG. SCRIBING FD. - BARK BADLY
BURNED. - YELLOW TAG DATED 4/27/54.

FD. FIR STUMP (NOW 24" DIAM.)
S 42° W 27⁷ FT. - STUMP CUT LOW -
NO MKS. FD.

NO TRACE FD. OF S.E. B.T.

FD. FIR SNAG - 16" DIAM. & APPROX
10 FT. HIGH, SCRIBED IN WOOD

NOT ORIG
B.T.

"T225 R8W S7" S 77¹/₂° E 35³ FT.
YELLOW TAG DATED 4/27/54

FD. FIR STUMP - 20" DIAM. & 5 FT.

NOT ORIG
B.T.

HIGH - BARK SCRIBING FD. "T225
R9W S12 BT" S 65° W 27⁰ FT.

YELLOW TAG DATED 4/27/54

ALONGSIDE IRON PIPE AT COR.
SET IRON PIPE WITH BRASS CAP MKD.

"COUNTY SURVEYOR'S OFFICE 1963

T225 R9W S1/56 R8W"
S12/57

RESCRIBE - IN BARK - 45" DEAD
FIR N 45° W 4⁰ FT. MKD. "T225
R9W S1 CS BT"

NO LIVE TREES AVAILABLE,
SEPT. 25, 1963

W. E. Godfrey

M.G. - W.S. - M.S.

C. S. File No. 521 X .73

✓
X
⊙