

REN. T 22 S R 8 W

S. W. COR. DLC 42
S. E. COR. DLC 43

AT COR. FD. $\frac{1}{2}$ " PIPE SET BY

COLE IN 1915 - A NEW, GALV. $\frac{1}{2}$ " PIPE
& A $1\frac{1}{2}$ " GALV. PIPE ALONGSIDE.

FD. FIR - UP ROOTED & DOWN -

N $87\frac{1}{2}$ ° W 192 FT. - LYING FACE
DOWN.

NO TRACE FD. OF S. E. TREE.

BLAZE & SCRIBE NEW TREES:

5" DOUG. FIR N 85° W 125 FT.

MKD. " DLC 43 CS BT "

6" DOUG. FIR N 65° W 275 FT.

MKD. " DLC 43 CS BT "

NO TREES LARGE ENOUGH TO
MARK EAST OF LINE

COR. IS ON NOSE OF SMALL

SPUR, SLOPING VERY STEEPLY TO THE
NORTH, APPROX. 150 FT. SOUTH OF
FOOT OF HILL - AND DIRECTLY IN
LINE WITH A NEW FENCE LINE EXTEND-
ING FROM FOOT OF HILL NORTH TO THE
RIVER

SEPT. 10, 1964

SEE REN. # 37

& # 4

M. G.

W. S.

M. S.

Milo E. Godfrey

+ X O ✓

C. S. File No. 52/14 ⁴³