

REN. T 22 S R 8 W N.W. COR. D.L.C. 42  
N.E. COR. D.L.C. 43  
AT COR. F.D.  $\frac{1}{2}$ " IRON PIPE SET

BY BEN IRYING IN 1945 - PIPE BURIED  
APPROX. 1 FT. DEEP IN SAND.

F.D. STUMP OF WHITE OAK S 59° W  
42 3 FT. - SHOWS VERY PLAIN "BT"  
SCAR - DID NOT OPEN. - STUMP RECENTLY  
CUT.  
F.D. STUMP HOLE & ROTTED REMAINS  
OF ASH TREE N 87° W 65 3 FT. -  
TRUNK BURIED IN SAND.

BLAZE & SCRIBE NEW TREES:  
13" MAPLE N 47° W 4 5 FT.  
MKD. " NE D L C 43 C S B T "  
14" MAPLE S 5° W 30 8 FT.  
MKD. " NE D L C 43 C S B T "

NO TREES NEAR EAST OF LINE.  
IRON PIPE IS AT N. END. OF  
N. & S. FENCE LINE

SEE RENEWALS  
# 38 & # 5

SEPT. 10, 1964  
M.G.  
W.S.  
M.S.

*Paul E. Godfrey*