

REN. T 22 S R 7 W COR. 20 | 21
SECS. 29 | 28

AT COR. FD. 2" IRON PIPE.

FD. FIR TREE (NOW 60" DIAM.)

S 52° W 67 ³/₄ FT. HAD BEEN OPENED
PREVIOUSLY & OLD FACE VISIBLE.

GOOD REVERSE SCRIBING "B" FD. ON
CHIP LYING IN NOTCH.

FD. BADLY ROTTED FIR STUMP
N 42° W 126 ⁷/₈ FT. NO SCRIBING FD.

FD. OLD FIR STUMP (48" DIAM.)
S 67° E 133 ³/₄ FT. DID NOT CHOP OPEN.
DID NOT SET BRASS CAP.

BLAZE & SCRIBE NEW TREES:

15" DOUG. FIR S 27° E 40 ³/₄ FT.
MKD. "T 22 S R 7 W S 28 CS BT"

29" DOUG. FIR S 4° W 30 ⁶/₈ FT.
MKD. "T 22 S R 7 W S 29 CS BT"

23" DOUG. FIR N 12 ¹/₂° W 116 ⁸/₈ FT.
MKD. "T 22 S R 7 W S 20 CS BT"

20" DOUG. FIR N 54° E 110 ⁹/₈ FT.
MKD. "T 22 S R 7 W S 21 CS BT"

MAR. 19, 1962

M.G.

Milo

ROYEVILVOR COUNTY INVEYOR
AND PUBLIC SALE

0
+ * ✓

C.S. File No. 52/14-126