



UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
State Office
710 N. E. Holladay
Portland 12, Oregon

IN REPLY REFER TO:

100.4a
ENG 9

January 28, 1963

Fred M. Darby
County Surveyor
Douglas County
Roseburg, Oregon

Dear Mr. Darby:

Reference is made to your letter of January 24, 1963, concerning the description of the northeast corner of Township 23 South, Range 9 West, Willamette Meridian. We have checked the records, and find the description of the corner at the end of the field notes of the original survey of the south boundary of T. 22 S., R. 9 W., executed by William H. Byars, in 1878. A copy is enclosed.

This was the first of the three township corners to be established. In 1881, Byars established the SW. corner of T. 22 S., R. 8 W., by projecting the south and west boundaries of that township, but made no reference to the 1878 corner. In 1894 Williams R. Whipple established the NW. corner of T. 23 S., R. 8 W., on the east boundary of T. 23 S., R. 9 W., at a point 8.75 chs. West of the SW. corner of T. 22 S., R. 8 W. The distance of 11.19 chs. on his plat (to the 1878 corner) was apparently obtained indirectly from his measurement to the Byars 1/4 section corner of Section 6, so no re-description was given of it. Similarly the Gesner-Worrick 1894 retracement of a portion of the south boundary of T. 22 S., R. 9 W., stopped at the Byars 1/4 section corner of Section 1, and the distance from there easterly to the 1878 township corner appears on the Gesner plat as 40.00 chs. Thus the only description of what is now the NE. corner of T. 23 S., R. 9 W., is the original one by Byars.

Sincerely yours,

Thomas A. Tillman

Thomas A. Tillman
Chief, Branch of Cadastral
Engineers

Enclosure

00 62/146 9
C. S. File No. 52/14

Extras were attempts to get more legible copies

483

Tat

484

Subdivisions of Township No. South Range
East Willamette Meridian, Oregon.

Subdivisions of Township No. South Range
East Willamette Meridian, Oregon.

16	00	Land at top broken 3d note. Correct in all particulars.
34	00	East on South boundary of sheet 35. (Correct from 1700)
40	00	Top of ridge c. S.
40	00	" " Ridge c. S. 20' 6" N. W.
40	00	Slip in post 5 in dia 4 feet long 20 in in ground from which
53	00	Apr 16 in dia 6 in East 35' 6" in dia
58	00	" " 8 " " West 52 " "
53	00	Top of ridge c. S. 15' 6"
50	00	Slip in post 4 in dia 40 in long for the cement. Station 2, 3, 4, 5, 6, from which
		Apr 30 in dia 6 in East 45' 6" sheet 10. Correct
		" " 30 " " S 40' 6" " 7 "
		" " 12 " " S 70' 6" " 50 "
		" " 18 " " N 80' 6" " 36 "
		Land mountains 3d note. Correct

25	00	East on South boundary of sheet 35
40	00	Correct sheet 35. Station 1700
40	00	S. 1 Cedar post 5 in dia 4 feet long
40	00	18 in in ground for the 4 2000 line from which
40	00	A pin 3 1/2 in dia 6 in East 30' 6" sheet 23. Correct
40	00	" Cedar 18 " " South " 45 "
40	00	Correct 3 lbs wide c. S. 33' 6"
52	00	" 4 " " " 4 " "
62	50	" 5 " " " 40 "
80	00	Slip in post 3 in dia 4 feet long
80	00	20 in in dia. 11 months cement. Township
80	00	22 x 23 3 in dia. Range 589 feet from which
80	00	Apr 36 in dia. 6 in East N 20' E sheet 24. Correct
80	00	" Cedar 12 " " S 70' E " 40 "
80	00	" pin 20 " " " S 50' W " 24 "
80	00	" " 24 " " " N 88' N " 29 "
80	00	NOTE: Post sets on top of ridge -
80	00	Land mountains - 3d note. Correct
80	00	Slip in post 4 in dia 40 in long

16 00	Land slope below 1st rate. Cont. in all the canyon.
34 00	East in South boundary of Sect. 35. (Barren from 1890 to 1892)
40 00	Top of spur C. S.
40 00	" " Ridge c. 200' E. of A. B.
52 00	Set in post 5 in diam 4 feet long 20 in in ground of same wheat.
58 00	Apr 15 in dia 6 in post 15 in dia
63 00	" " 8 " " " post 32 " "
80 00	Top of ridge c. 175' E
	Set in post 4 in dia 40 in long for the corner to station 1, 2, 3 & 4 25, from which
	Apr 30 in diam bear A 45° E about 10. Center
	" " 30 " " " S 40° E " 7 "
	" " 12 " " " S 70° W " 50 "
	" " 18 " " " A 80° W " 36 "
	Kind of timber 3 1/2 in dia. Timber quality 1st.

25 00	Set in South boundary of Sec 35
40 00	Break 1st. B. c. station 1700
	Set in post 5 in diam 4 feet long
	15 in in ground for the 4 sec corner from corner
	Apr 30 in diam bear A 30° W about 25 in dia.
	" " 18 " " " South " 15 "
41 00	Break 3 lbs wide c. A 35° E.
52 00	" " 4 " " " " " "
62 50	" " 5 " " " " " A 45°
80 00	Set in post 3 in dia 40 feet long
	20 in in ground of same timber corner to Township
	22 & 23 South Range 5 & 9 feet from which
	Apr 30 in dia bear A 20° E about 24 in dia
	" " 12 in " " " S 70° E " 40 "
	" " 20 " " " " S 30° W " 24 "
	" " 24 " " " " A 85° W " 28 "
	Post set in top of ridge -
	Kind of timber 3 1/2 in dia. Timber quality 1st.

15 00	Land stake broken 3/4 rate. West in the canyon.
34 00	West side South boundary of block 33 (Vanastrom. 1906)
40 00	Top of upper C. S. " " Ridge c 450° E. 4 W.
40 00	Top of post in diam 4 feet by 20 in ground from which
53 00	Apr 15 in diam bear East 35° East " " 8 " " West 32 " "
80 00	Top of ridge c 475° E Top of post 4 in diam 40 in high for the lower 40 feet. 2. 157 35. from which
" 30 "	Apr 30 in diam bear S 45° E about 10. diam " " 30 " " S 40° E " 7 " "
" 12 "	" " 12 " " S 70° W " 50 " "
" 18 "	" " 18 " " S 50° W " 36 " "
	Land stake broken 3/4 rate. South partly in

25 00	Cart	in South boundary of block 33 break 1/2 in diam 170° E
40 00	Set Cedar post 3 in diam 4 feet 18 in in ground for the 4 200 C. S. from 170° E Apr 30 in diam bear S 30° W about 25 in	
41 00	"	Cedar 18 " " South " 45 "
62 00	"	Cedar 3 lbs wide c 433° E. " 4 " " " " "
62 50	"	" 5 " " " " "
80 00	"	Set post 3 in diam for post to 20 in in ground 170° E corner of Dawson's 2272 3 South Range 589 feet from which Apr 30 in diam bear S 20° E about 20 in " Cedar post 12 in " " S 70° E " 40 " " " 20 " " " S 50° W " 24 " " " 24 " " " S 85° W " 28 " Post hole on top of ridge - Land stake broken 3/4 rate. South partly in