

RENEW 26/25
35/36

T 305 R6W

FOUND THREE ORIG. B.T.S. ALL
ON MARKHAMS B.T.S. ALSO N S
FENCE 2' EAST OF COR.

ORIG NW BT NOW ROTTED STUMP
BUT SHOWS GOOD REVERSE. SCRIBING "BT"
ORIG. SW BT NOW 24" W. OAK CENTER
ROTTED. ORIG. SE BT SHOWS GOOD
SCAR. MARKHAMS B.T.S. ARE BARK SCRIBED
AND HIS NW BT NOW LOW CUT FIR STUMP.

SET BRASS CAP AT CORNER MARKED
COUNTY SURVEYORS OFFICE 1960

524/525 T 305 R6W
535/536

NEW B.T.S.

RESCRIBED NOW 8' LAUREL 570' W
T 305 R6W S 35 C S B.T.

28" B. OAK S 42° E 58.7' (ORIG.)
SCRIBED T 305 R6W S 36 C S B.T.

9" W. OAK N 52° W 57.5'
SCRIBED T 305 R6W S 26 C S B.T.

10' W. OAK N 3° W 40.5'
SCRIBED T 305 R6W S 25 C S B.T.

FILED

RECEIVED

JUN 20 1960

JUN 24 1960

JUNE 24 - 1960

H. B.
M. G.
C. P.

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

*

✓✓

C.S. 52/25-5

DIETZGEN NO. 3885-6