

Review Sec. Cor  $\frac{516}{521} \frac{315}{522}$  T315 R6W

Fd. at Cor The following.

30" Now 38" Cor Tree - fir (snag) Badly  
Fire Scarred.

22" Now 30" Fir (Burned snag) N. 57° W. 14° ft.

We open & find nothing, probably Bark scribed.

40" Now 48" Fir (Burned snag) S. 35° E. 44° ft.

We open & find nothing, probably Bark scribed.

5" Now 8" Fir (Burned snag) N. 36° E. 10° ft.

Recorded as 8" originally - we open & find  
"T315 R6W 515" scribe. No trace of

Laurel BT. We set witness Cor. 4° ft

West, a 1" I.P. & Brass Cap MKd "COUNTY  
SURVEYORS OFFICE 1964 T315 R6W

W.C. 4 FT. E.  $\frac{516}{521} \frac{515}{522}$  " & MK New BTs -

5" D. Fir N. 42° W. 24° ft.

Mkd "W.C. 516 CS BT"

3" D. Fir N. 6° E. 4° ft.

Mkd "W.C. 515 CS BT"

4" D. Fir S. 58° E. 14° ft.

Mkd "W.C. 522 CS BT"

5" D. Fir S. 10° W. 23° ft.

Mkd "T315 R6W 521 WC CS BT"

No. Large Trees available.

Oct. 13, 1964

V.R.T.  
M.B.  
J.B.

+X O ~~ERRATA~~

C. S. File No. 52/25-25