

26 25

Renew Sec. Cor. 35 36 T255 RIW

Fd. orig. 5" Now 7" Hemlock Cor. Tree

2 live & good cond. Shows good scars
at Base of Tree - we do not open. also
find B.T.s as follows -

orig. 8" Now 15" Hemlock N. 89° E. 2° ft
shows good scar - 2 live - do not open.

orig. 12" Now 28" Hemlock S. 51° E. 14 1/2 ft.
Now stump, shows "S 36" scribe on
previously opened B122. No trace of
N.W. & S.W. B.T.s - Do not set BRASS cap.
MARK new B.T.s -

14" D. Fir S. 41° E. 50 1/4 ft.
MKd. " T255 RIW S 36 CS BT "

14" D. Fir S. 6° W. 45 1/2 ft.
MKd. " T255 RIW S 35 CS BT "

11" Chinquapin N. 82° W. 67 6/8 ft.
MKd. " T255 RIW S 26 CS BT "

This Cor. Lies on very steep
N. slope of hill. set 1/2" x 30" IR,
at Base of Cor. Tree, ~~M. F. E. D. E.~~

Oct. 14, 1966

RECEIVED

J.H.
OCT 14 1966

J.R. Tracy

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

75
* O.K. J.W. B

C. S. File No. 52/30-29