

Renew Sec. Cor. ^{T255 524} RIW 525 RIE

Fd. 1927 G. 40. BRASS CAP Properly

Mkd. & B.T.s as follows -

ORIG. 28" Now 36" W. FIR S. 14° W. 71 2/3 ft.

NOT S. 18° W. - shows SCRIBE MARKS ON
unhealed blaze - alive.

ORIG. 48" Now 53" FIR N. 18° W. 23 8/10 ft.

Dead & shattered - scribe MKs visible on
face & reverse ON overgrowth.

we MARK New B.T.s -

8" W. FIR S. 56° W. 11 2/3 ft.

Mkd. " T255 RIW 525 CS BT "

8" D. FIR N. 12° W. 46 4/10 ft.

Mkd. " T255 RIW 524 CS BT "

This COR. Lies on Southerly slope

approx. 360 S. of Top of S Pur. &

approx. 164 ft N. of Closing COR. of
Sec.'s 19 & 30 of T255 RIE.

Oct. 18, 1966

V.R.T.
J.H.
D.W.

FILED

RECEIVED

OCT 18 1966

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

C. S. File No. 52130-22

OK #68-RIW
#5-RIE