

Renew $\frac{1}{4}$ $\frac{513}{524}$ T255 R1W

Fd. STump of orig. COR. TREE, 25 50" FIR
shows 5 COR. & BTs recorded in Ren #13

as follows -

48" FIR (now STump) S, 38 $\frac{1}{2}$ ° W, 18 $\frac{8}{8}$ ft.
shows " $\frac{1}{4}$ 524 BT" scribe on unhealed
Blaze -

50" FIR (now STump) N, 38 $\frac{1}{2}$ ° E, 35 $\frac{3}{3}$ ft.
shows " $\frac{1}{4}$ 513 BT" on unhealed Blaze
orig BTs gone completely. We drive
 $\frac{1}{2}$ " x 30" I.P. in center of STump & set
1" I.P. & BRASS cap at base on West side
of COR. STump MKd "COUNTY SURVEYORS
OFFICE 1966 T255 $\frac{1}{4}$ $\frac{513}{524}$ R1W"
& MK. New BTs -

10" W. FIR N, 13 ° E 71 $\frac{6}{6}$ ft.
MKd " $\frac{1}{4}$ 513 cs BT"

6" I. Cedar N, 58 ° E, 84 $\frac{9}{9}$ ft.
MKd " $\frac{1}{4}$ 513 cs BT"

No TREES available in section 24.
Bearings & Distances I.R.

Oct. 21, 1966

FILED

RECEIVED

J. H.
D.W.

OCT 21 1966

J. R. Tracy

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.
C. S. File No. 52/30-36

#87 o.k. J.W.B.