

Found $\frac{1}{4}$ $\frac{511}{514}$ T255 RIW

Fd. ORIG. 4" Now 5" Hemlock N. 45° W. 7³ ft
previously opened & shows " $\frac{1}{4}$ 511"
scribe & good BT SCAR. also very
badly decayed Remnants of orig. 10"
Alder S. 56° W. 33 ft. No scribe Fd.

Find steel pipe with Alum. Cap MKd.
"U. S. P. C. PROPERTY COR. T255 RIW
 $\frac{11}{14}$ $\frac{1}{4}$ RE 4287" & New B.T.s 25 follows -
26" W. FIR N. 32 $\frac{1}{2}$ ° W. 30 ± ft.
scribed " $\frac{1}{4}$ 511 BT"

24" cedar S. 17° E. 43⁶ ft.
scribed " $\frac{1}{4}$ 514 BT"

New B.T.s & cap unrecorded.
This cor. lies approx 125 ft
west of Canton creek.

Nov. 2, 1966

V.R.T.
J.H.

FILED
RECEIVED

V.R. Tracy

OCT 31 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

D.K. J.W.B.

C. S. File No. 52/50-46