

Renew Township Cor. T245 RIW  $\frac{536}{51} | \frac{531}{56}$  RIE.

Fd. 211 orig. B.T.S as follows -

orig. 18" "Now 28" Cedar N. 64° E, 11<sup>2</sup> ft.

Previously opened many years ago. "S E 53"

scribe visible on nearly healed blaze

we Rescribe "T245 RIE 531 DCS BT"

orig. 28" "Now 36" Fir S. 37° E, 43<sup>6</sup> ft.

alive good cond. - shows very good scar.

orig. 30" "Now 36" Fir S. 86° W, 33<sup>0</sup> ft.

alive - good cond. - shows very good scar.

orig. 18" "Now 21" Fir N. 25° W, 31<sup>0</sup> ft.

alive - good cond. - shows very good scar.

Set 1" I.P. & Brass Cap MKd. DOUG. CO,

SURVEYOR'S OFFICE 1966 T245

RIW  $\frac{536}{51} | \frac{531}{56}$  T255 RIE" & MK New BT

16" Hemlock N. 60° W, 34<sup>8</sup> ft.

Mkd. "T245 RIW 536 DCS BT"

No smaller trees close to S.E. or S.W.

This cor. is on Douglas-Lane county

line.

**FILED  
RECEIVED**

Nov. 3, 1968

V.R.T.  
NOV 3 1968  
D.W.

**COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.**

*[Handwritten signature]*  
#58 - T24-1W  
#76 - T25-1W

C. S. File No. 52/30-47