

Renew $\frac{1}{4}$ 51 | T255RIW & RIE.

Fd. 1927 G.L.O BRASS CAP firmly set & properly MKd. & B.T.'s as follows -

ORIG. 30" FIR S. 50°E. 63 $\frac{1}{2}$ ft.

Now SMOG - This B.T. was obliterated in 1927 Rehealed Blaze, we use as Reference since Bearing to following B.T. does not check.

1927 8" now 14" Pine N. 76°W. (Not N. 62°W.)

145 ft. partial scribe MKs visible on

Nearly Healed Blaze, alive we Rescribe

" $\frac{1}{4}$ 51 CS BT "

1927 8" not 14" Chinyappin S. 35°W. 15 $\frac{1}{2}$ ft.

Fragmentary scribe MKs visible on

badly decayed & unhealed Blaze, alive.

we MK. New B.T. -

12" D. FIR S. 6°W. 22 $\frac{5}{8}$ ft.

Mkd. $\frac{1}{4}$ 51 CS BT "

This COR. Lies 25 ft. East of

New Logging Rd. course N. & S

CURVING TO S.E.

FILED

Nov. 4, 1966

RECEIVED

V.R.T.

J.H.

D.W.

NOV

4 1966

COUNTY SURVEYOR 32/30

DOUGLAS COUNTY, ORE.

[Handwritten signature]
17 - RIE
O.K. J.W.B.