

Renew Sec. Cor. <sup>510/511</sup> 515/514 T255 RIW

Fd.  $\frac{3}{4}$ " I.R. Buried approx. 14"

below surface of ground & B.T.s as follows  
see Ren. # 42 -

32" D. Fir N. 79° E. 8<sup>6</sup> ft.

Shows good scars - alive - do not open.

16" R. Cedar S. 1° W. 22<sup>8</sup> ft.

Shows "T255 RIW 515 CS BT" alive.

14" R. Cedar S. 26° E. 40<sup>3</sup> ft.

Shows "T255 RIW 514 CS BT"

Orig. MW. BT. Lying face down.

Set 1" I.P. MKd. COUNTY SURVEYORS

OFFICE 1966 T255 <sup>510/511</sup> 514/515 RIW"

Over I.R. & MK. New B.T. -

10" R Cedar N. 10° W. 60<sup>3</sup> ft.

Mkd. "T255 RIW 510 CS BT"

This cor. lies approx 100 ft.

East of Logging access Road at

2 S.W. cor. of Timber.

CAP MKD  
CORRECTLY  
PER BLM.  
7/28  
10/14  
5/17

Nov. 7, 1966

FILED

V.R.T.

RECEIVED

D.H.  
D.W.

NOV 1966

*(Signature)*

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

\* #90

OK. JWIB.

C. S. File No. 52/30-54