

Renew $\frac{1}{4}$ $\frac{533}{54}$ T245 R1W
 $\frac{54}{54}$ T255

Fd. only orig. B.T.s as follows -

14" Yew S, 82°E, 17 $\frac{8}{8}$ Ft. (slope)

SCRIBE visible on unhealed blaze.

36" W. Fir N, 55°W, 11 $\frac{2}{2}$ Ft.

25 Ft. high S Nag - scribe visible on unhealed blaze. We find NO TRACE

OF BRASS CAP RECORDED IN REN #47

Due to Logging, New B.T. in same

REN. Now knocked over. We set

1" I.P. & BRASS CAP MKD "COUNTY

SURVEYOR'S OFFICE 1966 T245

$\frac{1}{4}$ $\frac{533}{54}$ T255 R1W" & MK. New B.T.s -

6" Hemlock S, 29°W, 39 $\frac{9}{9}$ Ft.

Mkd. " $\frac{1}{4}$ 54 CS BT"

11" Hemlock N, 83°E, 60 $\frac{4}{4}$ Ft.

Mkd. " $\frac{1}{4}$ 533 CS BT"

This cor. lies on E.-W. cutting line cutoff to North approx. 300 Ft. East of small creek course S.W.

FILED

RECEIVED

91 or 9, 1966

U.P.M.T.

NOV 9, 1966
D.W.

[Handwritten signature]

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

*T25-495
*T24-459

C. S. File No. 5230-55