

Renew Sec. Cor. ⁵¹⁸ 517 ⁵¹⁹ 520 T255 R1E.

Fd. Orig. Cor. Tree, 2 10" Now 11" Fir
With SCARS on 2 appropriate sides - now
SNAG. & following B.T.s -

Orig. 8" Now 14" Fir N. 65° W. 5 ³/₈ ft.
Live - shows good SCAR -

Orig 10" Now 13" Fir S. 53° W. 5 ²/₈ ft.
Now shattered STUMP - Find Reverse SCAR.

Orig. 10" Now 14" Fir N. 35° E. 16 ⁵/₈ ft.
Now SNAG - shows good SCAR. -

No Trace of S.E. BT. - Set 1" I.P. &
BRASS cap on South side of COR Tree
1 ft. from center, MKd. "COUNTY

SURVEYORS OFFICE 1967 T255

⁵¹⁸/₅₁₉ ⁵¹⁷/₅₂₀ R1E " & MK. New B.T.s -

10" Fir. S. 76° W. 57 ⁷/₈ ft.

Mkd. "T255 R1E S 19 CS BT"

8" Fir S. 77° E. 30 ⁸/₈ ft.

Mkd. "T255 R1E S 20 CS BT"

8" Fir N. 66° E. 15 ⁸/₈ ft.

Mkd. "T255 R1E S 17 CS BT"

This cor. Lies on very steep SW. slope
50 ft. S. of Log Road

April 6, 1967

U.P.T.
J.H.
D.W.

J.O.S. File No. 52/30-77