

REN. T24SR1W

20 | 21
29 | 28

AT COR. FD. ORIG ROCK WITH
4 NOTCHES ON E. & 2 NOTCHES ON
E. EDGES. ROCK LYING LOOSE ON TOP
OF GROUND

FD. FIR TREE (NOW 27" DIAM.)

N 14 1/2° E 21 1/2 FT. HAS BEEN OPENED
RECENTLY. GOOD SCRIBING "T24SR
1W S21 BT" PLAINLY VISIBLE.

FD. FIR TREE (NOW 12" DIAM.)

N 4° W 16 1/4 FT. (INSTEAD OF 17 1/2 FT.)
HAS BEEN OPENED SEVERAL YEARS AGO.
SCRIBING VISIBLE "24SRW 20"
FACE SHOWS SIGNS OF DECAY ALTHOUGH
TREE IS ALIVE.

FD. FIR TREE (NOW 44" DIAM.) S10°W
(INSTEAD OF S40W)

31 1/2 FT. RECENTLY OPENED. GOOD SCRIB-
ING "T24SR1W S29 BT" VISIBLE.

FD. FIR TREE (NOW 45" DIAM.) S10°E
(INSTEAD OF S14°E)

37 1/2 FT. SHOWS GOOD AXE SCAR. DID NOT OPEN.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "T24SR1W COUNTY SURVEYOR'S
OFFICE 1961 S20 | S21"

S29 | S28

BLAZE & SCRIBE ONE NEW TREE

40" FIR N 22° W 10 1/2 FT. MKD. "T24SR1W

* S20CSBT"

C. SVEIN No. 52/424

SEPT, 21, 1961

Phil E. Godfrey

M. G.
V. T.
C. P.

DIETZGEN NO. 385-6

**FILED
RECEIVED**

SEP 22 1961

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE**