

REN.

T 24 S R 1 W

$\frac{1}{4}$ $\frac{S15}{S22}$

FD. BADLY ROTTED FIR STAKE
LYING ON GROUND BY COR. SOME
SCRIBING STILL VISIBLE " $\frac{1}{4}$ S" I
BELIEVE THIS IS ORIGINAL STAKE.

FD. FIR TREE (NOW 40" DIAM.)
N 52° W - (NOT N 52° E) 66 FT.
SHOWS VERY PLAIN AXE SCAR.

FD. FIR TREE (NOW 22" DIAM.)
S 54° W 33 $\frac{1}{2}$ FT. SHOWS VERY PLAIN
AXE SCAR. DID NOT PENETRATE TREE.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "COUNTY SURVEYOR'S OFFICE
1962 T 24 S R 1 W $\frac{1}{4}$ $\frac{S15}{S22}$ "

BLAZE & RESCRIBE 22" DOUG. FIR
S 54° W 33 $\frac{1}{2}$ FT. MKD. " $\frac{1}{4}$ S 22 CSBT"

BLAZE & SCRIBE ONE NEW TREE:
7" WHITE FIR N 5° E 31 $\frac{1}{2}$ FT
MKD. " $\frac{1}{4}$ S 15 CSBT"

AUG 20, 1962

M.G.
V.T.
M.S.

M.G.
E. Coffey

+ * V ✓

C.S. No. 52/42-20