

Taken on phone by Darby

NOT RENEWED

FD. B.T.S. NOV. 5, 1962

DO NOT BELIEVE THIS IS

1/4 COR. - ~~1/4 COR.~~

Sec. 2 T24-R1 E 1/4

3 BT's., scribed - Jeep Road to Selena Mt.

NICKLIN, - 1896

T 24 S R I W N. BET. 35 & 36

68.25 BANK OF MCKINLEY CREEK, 30 LKS., S.E., ASCEND

26 | 25
35 | 36

80.00 SET PINE POST

6" FIR N18°E 45 LKS. (T24SR1W S25 BT) ⁽²⁹⁾

6" FIR S42°E 25 LKS. (T24SR1W S36 BT) ⁽¹⁶⁾

6" FIR S34°W 57 LKS. (T24SR1W S35 BT) ⁽³⁴⁾

48" FIR N64°W 66 LKS. (T24SR1W S26 BT) ⁽⁴³⁾

COR. IS ABOUT 40 FT ABOVE CREEK, ON SPUR SLOPING W.

25.2 CHS. E. TO CREEK, 10 LKS., N.W.

.50 CHS N. TOP OF SPUR, 10 FT. ABOVE SEC. COR., SLOPING W.

9.90 ONE W. CREEK BOTTOM, N. 45. 50 FT. BELOW SEC. COR.

15.65 CHS. W. MCKINLEY CREEK, S.

T 25 S R I W N. BET. 25 & 26

JOHNSON - 1900

66.50 SPUR, E.

76.65 SPR. BR., 1 LK, E - ALONG STEEP E. FACE

80.00 SET BASALT STONE - 18" X 8" X 6" 12" IN GROUND

23 | 24
26 | 25

2 NOTCHES S., 1 NOTCH E.

FD. 3/4" ROD 10" FIR N35°E 11 LKS. (T25SR1W S24 BT) 12 1/2

AT COR. 5" HEM. S43°E 11 " (T25SR1W S25 BT) 7 3/4

ALL ORIG. 5" HEM. S75°W 15 " (T25SR1W S26 BT) 9 1/2

6" HEM. N61°W 22 " (T25SR1W S23 BT) 14 1/2

B.T.S. ALIVE

& STANDING

SCRIBE VIS. ON S.W. TREE

ALL OTHERS SHOW GOOD SCARS

E. APPROX 7 CHS. TO CANTON CREEK

N. 2 CHS. TO CANTON CREEK

W 2 CHS. TOP OF SPUR

N. BET. 19 & 20

PRICE - 1944

70.80 BRANCH, 3 LKS. N.W

84.16 BRASS CAP

T25SR3W

518 | 517

519 | 520

12" FIR N16 1/2°E 95 LKS. ⁽⁶²⁾

12" FIR S64 1/2°E 48 " ⁽³¹⁾

20" R. CED. S43°W 13 " ⁽⁸⁶⁾

42" FIR N49°W 67 " ⁽⁴⁴²⁾

ORIG. 18/17
19/20 ⁽¹⁴⁵⁾

30" FIR N10°E 22 LKS. ⁽³⁸⁹⁾

6" FIR S70°E 59 " ⁽¹⁴⁵⁾

12" FIR S33°W 22 " ⁽²¹⁾

15" FIR N40°W 32 " ⁽²¹⁾

WHEELER - 1883

FILED
RECEIVED

OCT 31 1962

COUNTY SURVEYOR
DOUGLAS COUNTY, NEB.

C.S. File No. 52-12-30

L. Duncan

Request to County Surveyor for Cadastral
Corner renewal

10/29/62

① Sec 35, T 24 S, R 15 W, S 1 M.

COR. RENEWED NOV. 5, 1962
Mils E. Jeffrey
NE Corner

BT: 8" DF 30' N 32 E

Location: Canton Co Road to tag on stump
Go East ± 1000 ft to 2nd growth
Timber

~~② Sec 25, T 25 S, R 15 W, S 1 M.~~

FD. COR. D.K. NOV. 7, 1962
DOES NOT NEED RENEWING
Mils E. Jeffrey

Corner: 1" Iron Pipe

B.T.s:

7" Hemlock 15 ft N 75 E

11" Hemlock 17 ft S 65 E

Location: Canton Co Road to bridge
just before park corner is
west of road

③ Sec 19, T 25 S, R 32 W, S 1 M

COR. RENEWED NOV. 7, 1962
Mils E. Jeffrey
NE Corner

Corner: 1" Iron Pipe

B.T.: 19" S.G.C. 9 ft

Location: North edge of road on cutting
(over) Boundary up Slide Cr.

C.S. File No. _____