

Renew  $\frac{1}{4}$   $\frac{524}{525}$  T245 RIW

Fd. ONE ORIGINAL BT alive & other  
BT down & Badly Rotted &

18" Now 22" Hemlock S. 72° E. 3<sup>3</sup> ft.

open & shows " 4 5 " scribe. alive.

20" Fir N. 40° E. 17<sup>8</sup> Ft. (Down)

fragments of old face visible.

we set 1" I.P. & BRASS CAP MKD.

"COUNTY SURVEYOR'S OFFICE 1965

T245  $\frac{1}{4}$   $\frac{534}{525}$  RIW" & MK new BT-

10" Hemlock N. 22° E. 54<sup>4</sup> ft.

Mkd "  $\frac{1}{4}$  524 CS BT"

This COR. Lies on steep East  
slope approx 230° ft West of Creek.

June 16, 1965

U.R.T.  
T.C.

 FILED  
RECEIVED

JUN 16 1965

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

OK  
+X

C. S. File No. 52/42-37