

524 | 519
Renew Sec. Cor. 525 | 530 T245 RIW & RIE

Fd. Basalt/stone 12" x 8" x 16" with 4

Notches on N. Edge & 2 Notches on S.

Edge firmly set ~~to~~ 3 original BTs

36" Now 42" FIR N. 60° E. 38² ft. (Face)

alive - shows good SCAR.

30" Now 52" FIR S. 58° E. 44² ft. (Face)

alive - shows good SCAR.

12" Now 17" FIR N. 79° W. 66² ft. (Face)

alive - open & shows "T2 S R. 524 BT"

Rotting due to INJURY - We set 1" I.P. & BRASS cap MKd "Dougl. Co. SURVEYOR'S OFFICE 1965 T245 RIW

524 | 519
525 | 530 RIE"

& set Rock along side. MARK new BTs -

10" Hemlock N. 69° W. 19² ft.

Mkd. "T245 RIW 524 DCS BT"

10" Hemlock S. 73° W. 21⁵ ft

Mkd. "T245 RIW 525 DCS BT"

This COR. IS ON Douglas-Lane Co. Line.

June 17, 1965 FILED V.R.T.
RECEIVED^c

JUN 17 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 52/42-38

+* 0