

Renewal

S 11 S 12  
S 14 S 13

7315 R3W

Found:

No Trace of I Pipe at cor.  
12" Laurel now 13" N 89 E 17 3/4  
Scribe visible

5" Fir N 13 E 7 9  
No Trace of this tree

6" Fir N 49 W 1 9  
No Trace of this tree

6" Laurel S 21 W 10 9  
No Trace of this tree

6" Fir now 8" S 18 E 12 6  
Scribe visible BT

2 1/2" Fir O.B.T. now 30" N 86 W 59 3/4  
Shows good Face

Renewed

Set Brass cap at Sec. cor. M&M

County Surveyors Office

7315 R3W

S 11 S 12  
S 14 S 13

1965

New Bearing Tree

8" Laurel S 61 W 20 6  
Scribed 7315 R3W S 14 S 13 BT

This cor. Falls in Fire Trail, therefore  
Destructing some bearing trees

12-10-65

(Renewal #56)

*[Handwritten signature]*

#105

DIETZEN NO. 385-6